

00862.022223.



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
TETSUYA KAWANABE) Examiner: T. Lett
Appl. No.: 09/853,710) Group Art Unit: 2625
Filed: May 14, 2001)
For: IMAGE PROCESSING SYSTEM,)
IMAGE DATA PROCESSING)
METHOD, AND STORAGE MEDIUM)
U.S. Patent No.: 7,068,386 B2)
Issued: June 27, 2006) May 29, 2007

Certificate
JUN 04 2007
of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR
CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

05/31/2007 JADDO1 00000105 7068386


01 FC:1811

100.00 OP

JUN - 4 2007

Patentee's undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,


Damond E. Vadhais
Attorney for Patentee
Registration No.: 52,310

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

FCHS_WS 850617v1

JUN - 4 2007

JUN - 4 2007

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 7,068,386 B2

DATED : June 27, 2006

INVENTOR(S) : Tetsuya Kawanabe

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

DRAWINGS:

Sheet 28, Figure 28A, Box S306, "GENELTATE" should read -- GENERATE --.

COLUMN 23:

Line 49, " \leftarrow -43" should read -- \longleftrightarrow --.

COLUMN 24:

Line 22, "circuit" should read -- circuit) --; and

Line 44, "print S" should read -- print --.

COLUMN 25:

Line 3, "(PCMD" should begin a new paragraph; and

Line 60, " "N"- "H", " should read -- "N"="H"; --.

COLUMN 29:

Line 3, "AckReplyok" should read -- AckReplyOk --.

COLUMN 32:

Line 45, " (1) " should read -- (4) --.

COLUMN 36:

Line 18, "plyok," should read -- plyOk, --.

COLUMN 37:

Line 30, "plyok," should read -- plyOk, --;

Line 50, "AckReplyok," should read -- AckReplyOk, --; and

Line 57, "plyok" should read -- plyOk --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,068,386 B2

No. of add'l. copies
@ 30¢ per page

JUN 14 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 7,068,386 B2

DATED : June 27, 2006

INVENTOR(S) : Tetsuya Kawanabe

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 38:

Line 62, "AckReplyok" should read -- AckReplyOk --.

COLUMN 39:

Line 25, "AckReplyok" should read -- AckReplyOk --; and

Line 46, "Replyok" should read -- ReplyOk --.

COLUMN 40:

Line 3, "AckReplyok" should read --AckReplyOk --.

COLUMN 46:

Line 46, "recoded" should read -- recorded --.

COLUMN 49:

Line 53, "e.g." should read -- e.g., --.

COLUMN 52:

Line 66, "devices" should read -- device --.

COLUMN 59:

Line 1, " is a" should read -- is --.

COLUMN 60:

Line 7, "is a" should read -- is --.

COLUMN 64:

Line 12, "program," should read -- programs, --; and

Line 46, "users" should read -- user --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,068,386 B2

No. of add'l. copies
@ 30¢ per page

123149-3000

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 7,068,386 B2

DATED : June 27, 2006

INVENTOR(S) : Tetsuya Kawanabe

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 66:

Line 36, "function" should read -- function, --.

COLUMN 67:

Line 14, "stop" should read -- step --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,068,386 B2

No. of add'l. copies
@ 30¢ per page

JUN - 4 2006

→ _____

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 7,068,386 B2

DATED : June 27, 2006

INVENTOR(S) : Tetsuya Kawanabe

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

DRAWINGS:

Sheet 28, Figure 28A, Box S306, "GENELTATE" should read -- GENERATE --.

COLUMN 23:

Line 49, " \leftarrow -43" should read -- $\leftarrow\rightarrow$ --.

COLUMN 24:

Line 22, "circuit" should read -- circuit) --; and

Line 44, "print S" should read -- print --.

COLUMN 25:

Line 3, "(PCMD" should begin a new paragraph; and

Line 60, " "N"- "H", " should read -- "N"="H"; --.

COLUMN 29:

Line 3, "AckReplyok" should read -- AckReplyOk --.

COLUMN 32:

Line 45, " (1) " should read -- (4) --.

COLUMN 36:

Line 18, "plyok," should read -- plyOk, --.

COLUMN 37:

Line 30, "plyok," should read -- plyOk, --;

Line 50, "AckReplyok," should read -- AckReplyOk, --; and

Line 57, "plyok" should read -- plyOk --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,068,386 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
123149 (Form#30)

JUN 4 2007

→

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,068,386 B2

DATED : June 27, 2006

INVENTOR(S) : Tetsuya Kawanabe

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 38:

Line 62, "AckReplyok" should read -- AckReplyOk --.

COLUMN 39:

Line 25, "AckReplyok" should read -- AckReplyOk --; and

Line 46, "Replyok" should read -- ReplyOk --.

COLUMN 40:

Line 3, "AckReplyok" should read --AckReplyOk --.

COLUMN 46:

Line 46, "recoded" should read -- recorded --.

COLUMN 49:

Line 53, "e.g." should read -- e.g., --.

COLUMN 52:

Line 66, "devices" should read -- device --.

COLUMN 59:

Line 1, " is a" should read -- is --.

COLUMN 60:

Line 7, "is a" should read -- is --.

COLUMN 64:

Line 12, "program," should read -- programs, --; and

Line 46, "users" should read -- user --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,068,386 B2

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 7,068,386 B2

DATED : June 27, 2006

INVENTOR(S) : Tetsuya Kawanabe

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 66:

Line 36, "function" should read -- function, --.

COLUMN 67:

Line 14, "stop" should read -- step --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,068,386 B2

No. of add'l. copies
@ 30¢ per page